

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Mt. Calvary Learning Center**

City: **Huron**

Provider Number: **014512585**

Inspector: **Neal Cruse**

Date of Inspection: **03/14/2024**

Time of Inspection: **8:49 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

<p>Corrections To Be Made:</p> <p>NW exit to the outside does not open properly. Panic bar is hard to push, and door drags on concrete.</p> <p>Exits and exit corridors must be maintained in a safe manner.</p> <p>Verification that the programs exit has been maintained was received.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">04/01/2024</td> <td style="text-align: center;">05/07/2024</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	04/01/2024	05/07/2024
Suggested Completion Date:	Actual Completion Date:				
04/01/2024	05/07/2024				

Jamie Lysne

Provider Signature

03/14/2024

Date

Neal Cruse

Inspector Signature

03/14/2024

Date