

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Busy B's 1**

City: **Chamberlain**

Provider Number: **014512627**

Inspector: **Russ Lauritsen**

Date of Inspection: **08/29/2024**

Time of Inspection: **9:37 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## Miscellaneous Rule Violations

61:15:05:15 - Basement requirements.

Corrections To Be Made:	Agency Action:	
<b>There are several breaches in the basement ceiling sheetrock protecting the floor joists.</b>	<b>Compliance Plan</b>	
<b>If the construction of the floor joists separating the basement from the first story consists of metal or wood, the framing shall be enclosed on the basement side.</b>	Suggested Completion Date:	Actual Completion Date:
<b>The program has sent verification that the breaches in the basement ceiling sheetrock has been repaired.</b>	<b>10/25/2024</b>	<b>10/11/2024</b>
	Status: <b>Corrected</b>	

**Blakely Nagy**

Provider Signature

**08/29/2024**

Date

**Russ Lauritsen**

Inspector Signature

**08/29/2024**

Date