

Family Day Care Inspection Compliance Plan

Provider's Name: **Alice Pike**

City: **Rapid City**

Provider Number: **016515778**

Inspector: **Robert Weig**

Date of Inspection: **03/27/2024**

Time of Inspection: **8:12 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

C. Health and Safety Features of the Home- Indoor Environmental Observations

53. If a fuel burning appliance is present in the home, is there a carbon monoxide detector installed according to the manufacturer ' s directions? 67:42:17:37

Corrections To Be Made:	Agency Action:	
Provider did not have a carbon monoxide detector in the home.	Compliance Plan	
Provider will need to install a carbon monoxide detector according to the manufacturer's directions.	Suggested Completion Date:	Actual Completion Date:
Corrections: Provider installed a carbon monoxide detector in the home according to the manufacturer's directions.	04/07/2024	04/08/2024
	Status: Corrected	

Alice Pike

Provider Signature

03/27/2024

Date

Robert Weig

Inspector Signature

03/27/2024

Date