

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Children's House Montessori**

City: **Rapid City**

Provider Number: **016597783**

Inspector: **Ann Marie Sailer**

Date of Inspection: **10/05/2023**

Time of Inspection: **8:02 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

19. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 61:15:01:01

<p>Corrections To Be Made:</p> <p>Items in the bathroom and art storage areas have items stored too close to the ceiling and sprinkler head.</p> <p>Combustible items needs to be stored at least 18 inches below sprinkler heads or 2 feet below the ceiling.</p> <p>Correction: Program removed items ensuring 18 inches below sprinkler heads and 2 feet below the ceiling.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">10/19/2023</td> <td style="text-align: center;">11/01/2023</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	10/19/2023	11/01/2023
Suggested Completion Date:	Actual Completion Date:				
10/19/2023	11/01/2023				

Michelle Kagamanov
Provider Signature

10/05/2023
Date

Ann Marie Sailer
Inspector Signature

10/05/2023
Date