

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Douglas YMCA Kidstop**

City: **Box Elder**

Provider Number: **016597823**

Inspector: **Jeremy Rieger**

Date of Inspection: **04/09/2024**

Time of Inspection: **6:49 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:	Agency Action:	
<b>A bin that contained playground equipment was blocking the entrance to the playground.</b>	<b>Compliance Plan</b>	
<b>All exits must be maintained in a safe manner.</b>	Suggested Completion Date:	Actual Completion Date:
<b>The bin was removed immediately.</b>	<b>04/09/2024</b>	<b>04/09/2024</b>
	Status: <b>Corrected Immediately</b>	
<b>Did this non-compliance issue result in serious child injury or death? Yes</b>		

**Jeremy**

Provider Signature

**04/09/2024**

Date

**Jeremy Rieger**

Inspector Signature

**04/09/2024**

Date