

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **BETHESDA LUTHERAN CHURCH**

City: **Hot Springs**

Provider Number: **016597902**

Inspector: **Meredith Schrier**

Date of Inspection: **01/25/2024**

Time of Inspection: **10:22 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. Fire and Life Safety

12. In Licensed Programs caring for 21 or More Children - In corridors providing access to exits, do combustible decorations cover less than 10% of the wall area? 61:15:05:05

Corrections To Be Made:	Agency Action:	
<b>Walls have an excess of combustible items posted.</b>	<b>Compliance Plan</b>	
<b>Corridors providing access to exits can not exceed more than 10% of combustible decorations on the wall area.</b>	Suggested Completion Date:	Actual Completion Date:
<b>*Program removed the combustible papers and verification was sent to OLA.</b>	<b>02/14/2024</b>	<b>02/02/2024</b>
	Status: <b>Corrected</b>	

**MELDOY LEIBBRANDT**

Provider Signature

**01/25/2024**

Date

**Meredith Schrier**

Inspector Signature

**01/25/2024**

Date