

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Campus Learning Center for Children**

City: **Sioux Falls**

Provider Number: **018026052**

Inspector: **Todd Lowe**

Date of Inspection: **03/20/2024**

Time of Inspection: **11:27 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

<p>Corrections To Be Made:</p> <p>No carbon monoxide detector was installed in the building.</p> <p>A carbon monoxide detector is to be installed according to manufacturer's directions as there is a fuel fired furnace present at the facility.</p> <p>*Correction: A carbon monoxide detector has been installed in the facility.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">04/04/2024</td> <td style="text-align: center;">04/09/2024</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	04/04/2024	04/09/2024
Suggested Completion Date:	Actual Completion Date:				
04/04/2024	04/09/2024				

Judy Knadel

Provider Signature

03/20/2024

Date

Todd Lowe

Inspector Signature

03/20/2024

Date