

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Peace C.A.R.E.**

City: **Sioux Falls**

Provider Number: **018037458**

Inspector: **Todd Lowe**

Date of Inspection: **08/06/2024**

Time of Inspection: **10:54 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

An illuminated exit sign in the fellowship hall, which is used as a school-age dining room, is completely obstructed and the panic hardware wired shut so the door is not operable. The room is larger than 1000 sq. ft. and with the addition now has 3 exits that are illuminated.

All exit signs that are illuminated and identify as an exit must remain clear. More than 2 exits are not required for this space and the one in reference may be eliminated if it is never used. Doing so will require that all evidence of it being an exit door is removed.

***Correction: obstructions have been removed and signage designating the above referenced door as an exit has been removed.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

08/20/2024

Status: **Corrected**

Actual
Completion
Date:

09/09/2024

B. Environmental Health

39. Is there a hand sink in the same room, or in an unobstructed adjacent room, to wash hands after each diaper change? 67:42:17:33

Corrections To Be Made:

The handwashing sink nearest the diaper changing table in the infant room was not accessible and was not working due to plumbing issues, resulting in providers passing through a gate after diaper changes.

There must be a hand sink in the same room or in an unobstructed adjacent room to wash hands after each diaper change.

The hand sink was repaired and the the path cleared so it is accessible to providers.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

08/06/2024

Actual
Completion
Date:

08/06/2024

Status: **Corrected Immediately**

58. Is the playground equipment installed according to the manufacturer ' s instructions and in good repair? 67:42:17:35

Corrections To Be Made:

There are loose and missing bolts and nuts on the slide of the jungle gym on the larger playground.

Playground equipment must be installed according to the manufacturer's instructions and in good repair.

***Correction: missing bolts have been replaced and loose bolts have been tightened.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

08/16/2024

Actual
Completion
Date:

09/09/2024

Status: **Corrected**

Tara Foley

Provider Signature

08/06/2024

Date

Todd Lowe

Inspector Signature

08/06/2024

Date