

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Good News Childrens Center**

City: **Sioux Falls**

Provider Number: **018038530**

Inspector: **Todd Lowe**

Date of Inspection: **02/13/2024**

Time of Inspection: **11:19 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

The southwest exit corridor was blocked due to the presence of classroom items that were being prepared for disposal.

The exits and exit corridors cannot be obstructed.

The program cleared the exit corridor by removing the items that were obstructing the exit.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

02/14/2024

Actual
Completion
Date:

02/15/2024

Status: **Corrected**

B. Environmental Health

58. Is the playground equipment installed according to the manufacturer ' s instructions and in good repair? 67:42:17:35

Corrections To Be Made:

The two outdoor wooden play structures were not maintained in good repair. The west outdoor play structure had exposed screws, rotten boards, and unstable handrails. The other wooden play structure has a deteriorated plastic coating on the chain climber, creating pinch points.

The playground equipment must be installed according to the manufacturer's instructions and in good repair.

The two wooden play structures are unavailable for children to play on and are scheduled to be replaced by May 31, 2024.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

05/31/2024

Actual
Completion
Date:

05/01/2024

Status: **Corrected**

Tammy Westergaard

Provider Signature

02/13/2024

Date

Todd Lowe

Inspector Signature

02/13/2024

Date