

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Prodigy Learning Center**

City: **Dakota Dunes**

Provider Number: **018042118**

Inspector: **Stacy Wildermuth**

Date of Inspection: **10/27/2023**

Time of Inspection: **11:15 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

In the pre-toddler room, a crib was in front of the door with emergency exit signage above it.

Emergency exits cannot be blocked.

***Correction; The crib was immediately moved from in front of the exit during inspection. Director has reminded staff to keep exits cleared in case of emergency.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

10/27/2023

Actual
Completion
Date:

10/27/2023

Status: **Corrected Immediately**

Kathy Soldati

Provider Signature

10/27/2023

Date

Stacy Wildermuth

Inspector Signature

10/27/2023

Date