

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Central Baptist Preschool**

City: **Sioux Falls**

Provider Number: **018042174**

Inspector: **Todd Lowe**

Date of Inspection: **08/24/2022**

Time of Inspection: **11:53 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

| | | | | | |
|---|--|----------------------------|-------------------------|-------------------|-------------------|
| <p>Corrections To Be Made:</p> <p>Observed a restricted egress path of less than 36" in the P106 room. This classroom equipment was on wheels and moved immediately. Additional concerns were two fire doors that were blocked open by carpet/floor chinks.</p> <p>Exits cannot be obstructed. All rated fire doors must be able to shut freely and not held in the open position.</p> <p>Correction: the equipment was moved so the egress path is clear and fire doors are no longer blocked open.</p> | <p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%; border: none;">Suggested Completion Date:</td> <td style="width: 50%; border: none;">Actual Completion Date:</td> </tr> <tr> <td style="border: none;">08/24/2022</td> <td style="border: none;">08/24/2022</td> </tr> </table> <p>Status: Corrected Immediately</p> | Suggested Completion Date: | Actual Completion Date: | 08/24/2022 | 08/24/2022 |
| Suggested Completion Date: | Actual Completion Date: | | | | |
| 08/24/2022 | 08/24/2022 | | | | |

Melissa Ludens

08/24/2022

Provider Signature

Date

Todd Lowe

08/24/2022

Inspector Signature

Date