

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **St. Katharine Drexel School**

City: **Sioux Falls**

Provider Number: **018042355**

Inspector: **Todd Lowe**

Date of Inspection: **09/06/2022**

Time of Inspection: **4:38 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made:

Discovered that the foot legs on the double swing doors that are in the corridor between the sanctuary and the classrooms were down and rendered the exit swing impassible. It was discussed that this is common practice to put the legs down due to security concerns between the sanctuary and classrooms. This was corrected immediately by stowing the foot legs upright.

*Correction: Foot legs will be stored upright beginning immediately and moving forward.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

09/06/2022

Actual
Completion
Date:

09/06/2022

Status: **Corrected Immediately**

Katie Taylor

Provider Signature

09/06/2022

Date

Todd Lowe

Inspector Signature

09/06/2022

Date