

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **St. Katharine Drexel School**

City: **Sioux Falls**

Provider Number: **018042355**

Inspector: **Todd Lowe**

Date of Inspection: **10/30/2023**

Time of Inspection: **4:09 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

**There was no Carbon Monoxide detection within the program.**

**\*Correction: smoke detectors have been installed in the mechanical room.**

Agency Action:

### Compliance Plan

Suggested  
Completion  
Date:

**11/10/2023**

Actual  
Completion  
Date:

**11/27/2023**

Status: **Corrected**

**Megan Lofink**

Provider Signature

**10/30/2023**

Date

**Todd Lowe**

Inspector Signature

**10/30/2023**

Date