

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Trinity Learning Center**

City: **Hartford**

Provider Number: **018042574**

Inspector: **Todd Lowe**

Date of Inspection: **01/22/2024**

Time of Inspection: **11:10 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

<p>Corrections To Be Made:</p> <p>A carbon monoxide detector was present but not installed or in service at the time of the inspection.</p> <p>There must be a carbon monoxide detector installed according to the manufacturer's directions.</p> <p>The program installed a carbon monoxide detector.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">01/29/2024</td> <td style="text-align: center;">01/26/2024</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	01/29/2024	01/26/2024
Suggested Completion Date:	Actual Completion Date:				
01/29/2024	01/26/2024				

Tymarite Svenson

01/22/2024

Provider Signature

Date

Todd Lowe

01/22/2024

Inspector Signature

Date