

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Grand Fun Alley Learning Center**

City: **Sioux Falls**

Provider Number: **018042607**

Inspector: **Todd Lowe**

Date of Inspection: **02/13/2023**

Time of Inspection: **5:02 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:

Storage in the mop closet and the closet by the kitchen are less than the required 18" in a non-sprinklered room. The main floor does not have a fire suppression system. The storage in the mop closet has caused the heat detector to come off the ceiling mounting pad and is hanging by the wires. This needs to be resecured and the space to come into compliance.

Correction: The heat detector was placed back on the ceiling mounting pad.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

02/21/2023

Actual
Completion
Date:

02/21/2023

Status: **Corrected**

Heather Groos

Provider Signature

02/13/2023

Date

Todd Lowe

Inspector Signature

02/13/2023

Date