

Family Day Care Inspection Compliance Plan

Provider's Name: **Abigail Klemisch**

City: **Tea**

Provider Number: **018042618**

Inspector: **Sarah Boese**

Date of Inspection: **06/21/2024**

Time of Inspection: **9:48 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

C. Health and Safety Features of the Home- Indoor Environmental Observations

53. If a fuel burning appliance is present in the home, is there a carbon monoxide detector installed according to the manufacturer ' s directions? 67:42:17:37

Corrections To Be Made:	Agency Action:	
The provider did not have a carbon monoxide detector installed.	Compliance Plan	
If a fuel-burning appliance is present in the home, a carbon monoxide detector must be installed according to the manufacturer's instructions.	Suggested Completion Date:	Actual Completion Date:
The provider installed a carbon monoxide detector according to the manufacturer's directions.	07/01/2024	06/24/2024
	Status: Corrected	

Abigail Klemisch

Provider Signature

06/21/2024

Date

Sarah Boese

Inspector Signature

06/21/2024

Date