

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Discovery Learning Center South**

City: **Sioux Falls**

Provider Number: **018042657**

Inspector: **Sarah Boese**

Date of Inspection: **08/29/2023**

Time of Inspection: **1:55 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. Environmental Health

34. Is the hot water temperature at hand washing sinks used by children maintained at 120 degrees F or lower? 67:42:17:33

<p>Corrections To Be Made:</p> <p>At the time of the inspection, the hot water temperature in the handsinks measured at 135 degrees F.</p> <p>The hot water temperature at the handwashing sinks must be maintained at 120 degrees F or lower.</p> <p>Correction: The water temperature at the hand washing sinks in the kitchen and bathroom were turned down below 120 degrees.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">09/08/2023</td> <td style="text-align: center;">09/08/2023</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	09/08/2023	09/08/2023
Suggested Completion Date:	Actual Completion Date:				
09/08/2023	09/08/2023				

Chelsie Ludewig

08/29/2023

Provider Signature

Date

Sarah Boese

08/29/2023

Inspector Signature

Date