

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **LSS @ Here for Youth**

City: **Sioux Falls**

Provider Number: **018042746**

Inspector: **Patrick Waltman**

Date of Inspection: **12/02/2024**

Time of Inspection: **2:01 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

During the inspection, it was noted that a carbon monoxide detector had not been installed.

A carbon monoxide detector must be installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.

Correction: The provider confirmed the installation of a carbon monoxide detector.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

12/17/2024

Status: **Corrected**

Actual
Completion
Date:

12/12/2024

Kathy Iverson

Provider Signature

12/02/2024

Date

Patrick Waltman

Inspector Signature

12/02/2024

Date