

# Family Day Care Inspection Compliance Plan

Provider's Name: **Angel Benson**

City: **Yankton**

Provider Number: **018042781**

Inspector: **Stacy Wildermuth**

Date of Inspection: **05/25/2022**

Time of Inspection: **9:30 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## C. Health & Safety Features of the Home - Indoor Environmental Observations

69. Is the hot water temperature at hand washing sinks maintained at 120 degrees or lower?  
67:42:03:11.05

### Corrections To Be Made:

**Hot water was found at 125F at the bathroom sink downstairs. Hot water should be maintained at 120F or lower.**

**\*Correction: Water measured at 115 degrees.**

### Agency Action:

#### Compliance Plan

Suggested  
Completion  
Date:

**06/01/2022**

Actual  
Completion  
Date:

**07/12/2022**

Status: **Corrected**

76. For each level of the home used for the care of children, are there 2 unblocked exits, separate and remote from each other? 67:42:03:11.03 Note: Window wells or outside structures of building etc. cannot inhibit or prevent safe exiting.

### Corrections To Be Made:

**Window used as the emergency exit from the basement was found with the well cover impeding the opening of the window. Window well cover should not impede the opening of the window,**

**\*Correction: Cover has been removed.**

### Agency Action:

#### Compliance Plan

Suggested  
Completion  
Date:

**06/08/2022**

Actual  
Completion  
Date:

**07/12/2022**

Status: **Corrected**

**Angel Benson**  
\_\_\_\_\_  
Provider Signature

**05/25/2022**  
\_\_\_\_\_  
Date

**Stacy Wildermuth**  
\_\_\_\_\_  
Inspector Signature

**05/25/2022**  
\_\_\_\_\_  
Date