

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Pitter Patter Playhouse**

City: **Sioux Falls**

Provider Number: **018042828**

Inspector: **Todd Lowe**

Date of Inspection: **06/27/2024**

Time of Inspection: **11:42 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

The north exit corridor in building A is obstructed by a gate.

Exit corridors must be maintained in a safe manner. Gate must be removed.

***Correction: the gate has been removed from the corridor.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

06/30/2024

Actual
Completion
Date:

08/12/2024

Status: **Corrected**

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

There are no carbon monoxide detectors installed according the the manufacturer's directions.

Carbon monoxide detectors must be installed.

***Correction: Carbon monoxide detectors have been installed in the buildings.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

07/05/2024

Actual
Completion
Date:

08/12/2024

Status: **Corrected**

Michele Kuemper

Provider Signature

06/27/2024

Date

Todd Lowe

Inspector Signature

06/27/2024

Date