

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Kinder Academy**

City: **Sioux Falls**

Provider Number: **018042917**

Inspector: **Todd Lowe**

Date of Inspection: **01/09/2024**

Time of Inspection: **4:26 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

12. In Licensed Programs caring for 21 or More Children - In corridors providing access to exits, do combustible decorations cover less than 10% of the wall area? 61:15:05:05

Corrections To Be Made:

During the inspection, multiple doors were partially, more than 10%, or entirely covered with decorations.

The exit doors within the shared corridor must be maintained at less than 10% of the surface area.

The provider removed the decoration from the doors.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

01/09/2024

Actual
Completion
Date:

01/10/2024

Status: **Corrected Immediately**

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

The doors on the north side of the building were obstructed by ice and snow, preventing them from opening.

All the exits and exit corridors must be maintained to ensure safety.

The provider removed the obstructions, and the doors now open.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

01/10/2024

Actual
Completion
Date:

01/12/2024

Status: **Corrected**

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

During the inspection, there was not a carbon monoxide detector installed at the center.

A carbon monoxide detector must be installed when a furnace or fossil fuel-based appliances are present.

The center has installed a carbon monoxide detector as outlined in the manufacturer's instructions.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

01/16/2023

Status: **Corrected**

Actual
Completion
Date:

01/10/2024

Jennifer Schuette

Provider Signature

01/09/2024

Date

Todd Lowe

Inspector Signature

01/09/2024

Date