

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Kidz Cottage Learning Center**

City: **Lennox**

Provider Number: **018042960**

Inspector: **Sarah Boese**

Date of Inspection: **12/20/2023**

Time of Inspection: **5:41 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. Environmental Health

59. For a center program, is the outdoor play area enclosed with a fence that is at least 48 " high?
67:42:17:35

<p>Corrections To Be Made:</p> <p>The outdoor play area is divided into three sections by a fenced enclosure. However, due to construction the section nearest the building needs a few sections reinstalled.</p> <p>The outdoor play area must be enclosed with a fence at least 48" high.</p> <p>The outdoor play area is not currently in use.</p> <p>Due to the winter season, the provider will install the missing fence sections by May 31, 2024. Until the fence is installed around all outdoor play areas, the two play ground areas enclosed with a fence will be utilized for outdoor play.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">05/31/2024</td> <td style="text-align: center;">06/03/2024</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	05/31/2024	06/03/2024
Suggested Completion Date:	Actual Completion Date:				
05/31/2024	06/03/2024				

Kalie Hanisch

12/20/2023

Provider Signature

Date

Sarah Boese

12/20/2023

Inspector Signature

Date