

Facility Safety Inspection

Fire & Life Safety / Environmental Health

Before & After School Center - School Location

Compliance Plan

Provider's Name: **B&G Club of Yankton Academy** City: **Yankton**
Beadle School

Provider Number: **018043041**

Inspector: **Stacy Wildermuth** Date of Inspection: **08/12/2022**

Time of Inspection: **9:30 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

C. FOOD SERVICE

29. Does food preparation area have a sink, with running water? 67:42:11:33 NOTE: A bathroom sink cannot be used for this purpose.

<p>Corrections To Be Made:</p> <p>Staff only have access to the sinks in the restrooms for washing hands before serving. Hands should be washed in an area other than the restrooms before food preparation and serving.</p> <p>*Correction: Program is closed until summer of 2023. Floor plans have been submitted to gain approval for use of kitchen to wash hands.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">08/12/2022</td> <td style="text-align: center;">09/01/2022</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	08/12/2022	09/01/2022
Suggested Completion Date:	Actual Completion Date:				
08/12/2022	09/01/2022				

Koty Frick

 Provider Signature

08/12/2022

 Date

Stacy Wildermuth

 Inspector Signature

08/12/2022

 Date