

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Kids R Kids Prairie Hills**

City: **Sioux Falls**

Provider Number: **018043101**

Inspector: **Sarah Boese**

Date of Inspection: **11/01/2024**

Time of Inspection: **2:51 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

17. Are exit signs provided over each exit, and where necessary to identify a change in the direction of egress travel? 61:15:05:05; 61:15:06:05 NOTE: Exit signs must be interior or exterior illuminated or self-luminous.

Corrections To Be Made:

The exit sign above entrance to STEAM lab is not illuminating by battery or electricity.

Exit signs are to be interior or exterior illuminated or self-luminous.

Correction: The light switch that regulates the illumination of the exit sign will remain in the "on" position until a qualified electrician is able to address and repair the wiring issue.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

11/11/2024

Actual
Completion
Date:

11/04/2024

Status: **Corrected**

19. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 61:15:01:01

Corrections To Be Made:

The exit sign above entrance to STEAM lab was not operational at the time of the inspection.

Exit signs are to be interior or exterior illuminated or self-luminous.

Correction: The light switch that regulates the illumination of the exit sign will remain in the "on" position until a qualified electrician is able to address and repair the wiring issue.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

11/11/2024

Actual
Completion
Date:

11/04/2024

Status: **Corrected**

Mike Smith

Provider Signature

11/01/2024

Date

Sarah Boese

Inspector Signature

11/01/2024

Date