

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Bethel Lutheran After School Care**

City: **Sioux Falls**

Provider Number: **018043103**

Inspector: **Todd Lowe**

Date of Inspection: **10/30/2023**

Time of Inspection: **5:05 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

<p>Corrections To Be Made:</p> <p>The center did not have a carbon monoxide detector present in the facility.</p> <p>A carbon monoxide detector must be installed when a furnace or fossil fuel-based appliances are present.</p> <p>The center has installed a carbon monoxide detector in accordance with the manufacturer's instructions.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">11/10/2023</td> <td style="text-align: center;">11/08/2023</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	11/10/2023	11/08/2023
Suggested Completion Date:	Actual Completion Date:				
11/10/2023	11/08/2023				

Glenda Knuth

10/30/2023

Provider Signature

Date

Todd Lowe

10/30/2023

Inspector Signature

Date