

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Bethel Lutheran After School Program**

City: **Sioux Falls**

Provider Number: **018043103**

Inspector: **Todd Lowe**

Date of Inspection: **09/17/2024**

Time of Inspection: **5:02 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

<p>Corrections To Be Made:</p> <p>The center did not have a carbon monoxide detector present in the facility.</p> <p>A carbon monoxide detector must be installed when a furnace or fossil fuel-used appliances are present.</p> <p>Correction: The director was able to locate two carbon monoxide detectors on each level of the center.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%; border: none;">Suggested Completion Date:</td> <td style="width: 50%; border: none;">Actual Completion Date:</td> </tr> <tr> <td style="border: none;">09/24/2024</td> <td style="border: none;">09/18/2024</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	09/24/2024	09/18/2024
Suggested Completion Date:	Actual Completion Date:				
09/24/2024	09/18/2024				

Ann Krueger

09/17/2024

Provider Signature

Date

Todd Lowe

09/17/2024

Inspector Signature

Date