

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **HAYWARD ELEMENTARY CLC** City: **Sioux Falls**

Provider Number: **018043137**

Inspector: **Todd Lowe**

Date of Inspection: **08/23/2023**

Time of Inspection: **2:52 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. Environmental Health

32. Are bathroom facilities easily accessible? 67:42:17:33

Corrections To Be Made:

The restrooms nearest the gym were under construction and not accessible to children in care.

All bathroom facilities must be easily assessible to children.

***Correction: Construction to the restrooms have been complete; Children now have access to the restrooms.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

08/24/2023

Actual
Completion
Date:

09/11/2023

Status: **Corrected**

49. Are all walls, ceilings, floors, and equipment easily cleanable, kept clean and in good repair?
67:42:17:32

Corrections To Be Made:

Rooms 102,107 and 110 renovations were under construction at the time of the inspection.

Walls, ceilings, floors and equipment must be kept in good repair.

***Correction: Renovations to rooms 102, 107 and 110 have been completed.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

08/24/2023

Actual
Completion
Date:

09/11/2023

Status: **Corrected**

TAYLOR FECHNER

Provider Signature

08/23/2023

Date

Todd Lowe

Inspector Signature

08/23/2023

Date