

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Hayward Elementary CLC**

City: **Sioux Falls**

Provider Number: **018043137**

Inspector: **Todd Lowe**

Date of Inspection: **06/27/2024**

Time of Inspection: **9:00 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

19. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 61:15:01:01

Corrections To Be Made:

In the storage room by 102, combustible materials were stored less than 18 inches from the sprinkler head.

Combustible materials must be maintained at least 18 inches below sprinkler head deflectors.

***Correction: The box was removed during the inspection and corrected immediately.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

06/27/2024

Actual
Completion
Date:

06/27/2024

Status: **Corrected Immediately**

Todd Lowe

Provider Signature

06/27/2024

Date

Todd Lowe

Inspector Signature

06/27/2024

Date