

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Terry Redlin Elementary CLC**

City: **Sioux Falls**

Provider Number: **018043142**

Inspector: **Todd Lowe**

Date of Inspection: **12/11/2024**

Time of Inspection: **3:32 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

The northwest exit corridor of the gym was obstructed by a garbage can.

Exits to be maintained in a safe manner.

***Correction: The was corrected at time of inspection. Program staff were advised that the exits must be always remain unblocked.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

12/11/2024

Actual
Completion
Date:

12/11/2024

Status: **Corrected Immediately**

Kelli Jurgensen

Provider Signature

12/11/2024

Date

Todd Lowe

Inspector Signature

12/11/2024

Date