

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Hawthorne Elementary CLC**

City: **Sioux Falls**

Provider Number: **018043146**

Inspector: **Todd Lowe**

Date of Inspection: **12/09/2024**

Time of Inspection: **4:26 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

Exits and corridors to be maintained in a safe manner.

The exit door adjacent to room 264 does not have exit hardware.

***Correction: The exit door is connected with a magnetic closure and releases when fire alarm sounds.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

12/20/2024

Actual
Completion
Date:

12/30/2024

Status: **Corrected**

Delany Read

Provider Signature

12/09/2024

Date

Todd Lowe

Inspector Signature

12/09/2024

Date