

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Garfield Elementary CLC**

City: **Sioux Falls**

Provider Number: **018043147**

Inspector: **Todd Lowe**

Date of Inspection: **12/06/2024**

Time of Inspection: **3:28 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

A "Plinko Play-set" is in the hallway near the art room and is obstructing the exit path.

Exits are to be maintained in a safe manner.

***Correction: the play-set has been moved away from the exit path.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

12/07/2024

Actual
Completion
Date:

12/16/2024

Status: **Corrected**

Jessica Zahn

Provider Signature

12/06/2024

Date

Todd Lowe

Inspector Signature

12/06/2024

Date