

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Inspire Learning Center**

City: **Tea**

Provider Number: **018043198**

Inspector: **Sarah Boese**

Date of Inspection: **08/06/2024**

Time of Inspection: **10:50 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. Environmental Health

49. Are all walls, ceilings, floors, and equipment easily cleanable, kept clean and in good repair?
67:42:17:32

Corrections To Be Made:	Agency Action:	
Air return vents in the multipurpose room and hallway near the back door need to be cleaned.	Compliance Plan	
All walls, ceilings, floors, and equipment are to be easily cleanable, kept clean and in good repair.	Suggested Completion Date:	Actual Completion Date:
Correction: The provider cleaned the air returns in both the multipurpose room and the hallway.	08/12/2024	08/07/2024
	Status: Corrected	

Jana Shenk

Provider Signature

08/06/2024

Date

Sarah Boese

Inspector Signature

08/06/2024

Date