

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Bright Beginnings 1**

City: **Beresford**

Provider Number: **019521604**

Inspector: **Sarah Boese**

Date of Inspection: **11/03/2023**

Time of Inspection: **1:42 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

Carbon monoxide detector needs to be installed.

***Correction: detector has been installed.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

11/10/2023

Actual
Completion
Date:

11/16/2023

Status: **Corrected**

Kari Peterson

Provider Signature

11/03/2023

Date

Sarah Boese

Inspector Signature

11/03/2023

Date