

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Bright Beginnings 2**

City: **Beresford**

Provider Number: **019522722**

Inspector: **Sarah Boese**

Date of Inspection: **11/03/2023**

Time of Inspection: **2:40 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

**Carbon monoxide detector needs to be installed.**

**\*Correction: detector has been installed.**

Agency Action:

### Compliance Plan

Suggested  
Completion  
Date:

**11/10/2023**

Actual  
Completion  
Date:

**11/16/2023**

Status: **Corrected**

**Kari Peterson**

Provider Signature

**11/03/2023**

Date

**Sarah Boese**

Inspector Signature

**11/03/2023**

Date