

Provider required to post this report.

## Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Agape Daycare**

City: **Lemmon**

Provider Number: **016597739**

Inspector: **Ann Marie Sailer**

Date of Inspection: **10/23/2024**

Time of Inspection: **11:54 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

### B. Environmental Health

49. Are all walls, ceilings, floors, and equipment easily cleanable, kept clean and in good repair?  
67:42:17:32

Corrections To Be Made:	Agency Action:
The base board heater in the toddler room has pulled from the wall.	<b>Compliance Plan</b>
The walls and equipment must be in good repair.	Suggested      Actual Completion      Completion Date:              Date:
Correction: The program repaired the base board heater in the toddler room.	11/06/2024      12/10/2024
	Status: <b>Corrected</b>

### C. Food Service

67. Is there a dishwasher or a 3-compartment sink available for washing, rinsing, and sanitizing?  
67:42:17:25  
NOTE: Centers serving 20 or less children, may use a 2-compartment sink and a tub for sanitizing.

Corrections To Be Made:	Agency Action:
Program currently has a one compartment sink.	<b>Compliance Plan</b>
Program will need to replace the current sink with a three compartment sink.	Suggested      Actual Completion      Completion Date:              Date:
Correction: Program has decided not to use this kitchen in the building. Program will be using another kitchen located in the building that was approved for use and meets the dishwashing requirements.	11/06/2024      12/10/2024
	Status: <b>Corrected</b>



Provider Signature

**Tracy Fattarusso**

Name

**10/23/2024**

Date



Inspector Signature

**Ann Marie Sailer**

Name

**10/23/2024**

Date