

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Eagle Nest Learning Center**

City: **Wanblee**

Provider Number: **010605535**

Inspector: **Meredith Schrier**

Date of Inspection: **09/30/2024**

Time of Inspection: **1:26 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. Environmental Health

33. Are toilets and hand sinks kept clean and in good repair? 67:42:17:33

Corrections To Be Made:

Counter tops in bathrooms are warped under the laminate. Counter tops must be in good repair and easily cleanable.

***The countertops have been repaired.**

Agency Action:

Compliance Plan

Suggested Completion Date:	Actual Completion Date:
10/14/2024	12/18/2024
Status: Corrected	



Provider Signature

AGNES HIGH HORSE

Name

09/30/2024

Date



Inspector Signature

Meredith Schrier

Name

09/30/2024

Date